

REPORT FOR THE ROAD CREEK SYSTEM FOR JULY 1975

THERE WAS'NT MUCH CHANGE IN THE SITUATION ON THIS SYSTEM DURING JULY. ALL THE WELLS WERE TURNED OF FOR ONE WEEK IN THE MIDDLE OF THE MONTH WHILE THE HAYING HARVEST WAS BEING DONE. DURING THE MONTHALL THE WELLS WERE CONTRIBUTING ABOUT ONE HALF OF THE FLOW TO MAINTAIN ROAD CREEK TO IT'S 5.80 CFS. SOME OF THE MEASURING DECICES HAVE NOT BEEN INSTALLED SO THERE CAN BE NO ACCURATE MEADUREMENT OF ALL THE WATER.

*Brant Chappell*  
*Commissioner*